8/7/2020

	BD FUEL INJECT	ION CORE ACCEPTANCE POLICY	
Model	Full Credit Criteria	Deduction	No Credit
P7100 Injection Pump	 All components present and assembled. Like for Like, application years & models must match. No external damage 	 AFC Housing Damaged (25% Deduction) Cracked or Damaged due to freight (50-100%) Governor Housing Damaged Front or Back (25% Deduction) Main Body Damaged (50% Deduction) 	 Contaminated/Bio Diesel Damaged Camshaft on 911/913 pumps. Excessive Rust or water damage Fire Damage Part disassembled
Bosch VE Pump	 All components present and assembled. Like for like No external damage No Fire Damage 	 AFC Housing Damaged (25% Deduction) Cold Advanced Housing Damaged (50% Deduction) Cracked or damaged due to freight (50-100%) Governor housing damaged front or back (25% deduction) Main Body Damaged (50% Deduction) Missing Parts (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized Head (Does not turn) Part disassembled
СРЗ	 All components present and assembled. Like for Like No Housing Damage 		 Contaminated/Bio Diesel Excessive rust or water damage Fire Damage Part disassembled Seized (Does not turn)
High Performance CP3	 All components present and assembled. No Housing Damage 		 Contaminated/Bio Diesel Excessive rust or water damage Fire Damage Part disassembled Seized (Does not turn)
VP44	 All components present and assembled. Like for like models Must be rebuildable 	 Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) 	 Contaminated/Bio Diesel Damaged Housing Excessive Rust or water damage Fire Damage Part disassembled
High Performance VP44	 All components present and assembled. Like for like models Must be rebuildable 	 Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) 	 Contaminated/Bio Diesel Damaged Housing Excessive Rust or water damage Fire Damage Part disassembled Solenoid melted or destroyed
Common Rail Injectors	 All components present and assembled. Body and threads are in good quality Like for like models Solenoid Broken plastic tabs allowed. 	• Solenoid melted or destroyed (25% Deduction)	 Contaminated/Bio Diesel Damaged Body Excessive Rust or water damage Fire Damage Part disassembled
Mechanical Injectors	 Body and threads are in good quality Like for like 	Jamage are not covered. Ensure you packaged the cor	 Contaminated/Bio Diesel Damaged Body Excessive Rust or water damage Fire Damage Part disassembled re sufficiently!

	BD TURBOCHARGER	CORE ACCEPTANCE POLICY	
Turbo Model/ Application	Full Credit Criteria	Deduction	No Credit
Cummins ISX VGT Air or Electronic Actuated	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled
Caterpillar (Ball Bearing) Models	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models, must have CAT logo 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled
Caterpillar (Standard Turbocharger) 704604-9007, 704604-9011)	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like, must have CAT or Garrett logo. 4 Support Webs 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Turbo with 3 support Webs Part Disassembled
Detroit Diesel VGT	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled

		8/7/2020
 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Damaged VGT cage due to turbine wheel explosion (50%) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged VGT cage due to turbine wheel explosion (50%) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
 All components present and assembled. Like for like models On Vehicle damage to compressor and turbine housing. On Vehicle damage due to Compressor & Turbine Wheel. 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
	 assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models All components present and assembled. Like for like models All components present and assembled. Like for like models On Vehicle damage to compressor and turbine housing. On Vehicle damage due to compressor & Turbine Wheel. 	 assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor & Turbine Wheel. Light or minimal damage to compressor & Turbine Wheel. Light or minimal damage to compressor & Turbine Wheel. Like for like models All components present and assembled. All components present and assembled. Light or minimal damage to compressor and turbine wheel. Like for like models All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Light or minimal damage to compressor and turbine housing. Like for like models All components present and assembled. Like for like models All components present and assembled. Like for like models All components present and assembled. Like for like models All components present and assembled. Like for like models All components present and assembled. Like for like models Cracked or Damaged Jue to freight (50-100%) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Missing Clamps (25% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Missing Parts or Actuators (50%

I-00434	8/7/2020		
	BD TRANSMISSION	I/TORQUE CONVERTOR CORE	
	ACCEPTANCE POLICY		
Model	Full Credit Criteria	Deduction	No Credit
Transmissions	 Dowel pin holes not damaged Drive shafts intact Like for Like Must be assembled No case cracks No external damage No missing pieces Threads not damaged 	 Missing electronics (25% Deduction) Cracked or heavily corroded extension/OD housings (50% Deduction) Broken shafts (Requires disassembly for accurate costing) 	 Catastrophic damaged Cracked Case Damaged input shaft area, destroyed pump, case and convertor area Excessive corrosion Fire damage Part disassembled
Torque Convertors	 No Rust No damage to Hub, Impeller and turbine Like for like 	 Hub and Impeller damaged. (50% Deduction) Modified/Aftermarket convertors in which the stator or turbine have been modified. (Only on purchased cores. 50% Deduction) 	 Excessive corrosion Seized Catastrophic failure Part disassembled
Valve Bodies	Like for likeNo missing parts	Missing electronics (25% Deduction)	Excessive corrosionPart disassembled

	GENERAL CORE ACCEPTANCE POLICY			
Model	Full Credit Criteria	Deduction	No Credit	
EGR Cooler	Like for like		 Bellows Damaged (dented, bent or perforated) 	
Freight and removal damage are not covered. Ensure you packaged the core sufficiently!				
Core must be rebuildable!				